



Transport Canada Civil Aviation
Standards Branch (AART)
330 Sparks Street
Ottawa, ON, Canada
K1A 0N5

Company File: 5015-19071
RDIMS: 15296421

Date: May 14, 2019

Jorge Viladoms
SAFRAN Aircraft Engine Services Americas S.A. de C.V.
Carretera Estatal 200, Querétaro Tequisquiapan km 22+547
Interior B1 & D2, Parque Aeroespacial Querétaro,
Municipio de Colon, C.P 76278. Querétaro, México

Subject: Acceptance of FAA-certificated Repair Stations located outside the United States

Dear Mr. Jorge Viladoms,

This letter authorizes SAFRAN Aircraft Engine Services Americas S.A. de C.V. Certification No. 3SMY129B to perform maintenance and modifications on aeronautical products, excluding aircraft, under TCCA regulatory control pursuant to Section B, Paragraph 4.0, of the FAA/TCCA Maintenance Implementation Procedures (MIP).

This authorization is limited to CFM56-5A/-5B/-7B engine series & LEAP-1A/-1B engine series manufactured by CFM International and the work performed must be within the ratings and limitations contained in your 14 CFR Part 145 certificate, operations specifications and capability list Revision 30, dated March 4, 2019. Any changes applied to your certificate, operations specifications, or capability list will invalidate this authorization and a new authorization request will be required by TCCA.

This TCCA authorization shall remain in effect until SAFRAN Aircraft Engine Services Americas S.A. de C.V. FAA Repair Station Certificate expires, September 30, 2020, or if the Certificate has been surrendered, suspended or revoked. In order to renew this authorization, TCCA requires SAFRAN Aircraft Engine Services Americas S.A. de C.V. to provide their renewed certificate, and demonstrate compliance with the MIP Section B, Paragraph 4.1, as part of their new authorization request.

Regards,

Gary Voght
Civil Aviation Safety Inspector
Operational Airworthiness, Standards